The Trail Inventory of Detroit Lakes WMD

Detroit Lakes, MN





Prepared By: Federal Highway Administration Central Federal Lands Highway Division February, 2012



TABLE OF CONTENTS

<u>SECTION</u>		<u>PAGE</u>
I.	TRAIL AND TRAIL FEATURE SUMMARIES	1 - 1
II.	TRAIL LOCATION MAPS	2 - 1
III.	TRAIL IDENTIFICATION LIST	3 - 1
IV.	TRAIL CONDITION RATING SHEETS	4 - 1
V.	TRAIL DEFICIENCY RATING SHEETS	5 - 1
VI.	PHOTOGRAPHIC SHEETS	6 - 1
VII.	GLOSSARY	i

Detroit Lakes WMD

Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

Trail Surface Type	Excel	lent	Othe	ers	Total
	Miles	%	Miles	%	Miles
Gravel	0.10	100%	0.00	0%	0.10
Asphalt	0.08	100%	0.00	0%	0.08
Boardwalk	0.04	100%	0.00	0%	0.04
Admin Road	0.00	0%	0.98	100%	0.98
Total	0.22	18%	0.98	82%	1.20

Trail Miles and Percentages by Trail Classification and Condition

Trail	Excel	lent	Othe	rs	Total		
Classification	Miles	%	Miles	%	Miles		
TC4	0.10	9%	0.98	91%	1.08		
TC5	0.12	100%	0.00	0%	0.12		
Total	0.22	18%	0.98	82%	1.20		

^{*}Admin Roads are included in the inventory but are not rated for condition.

Trail Features


Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T500	Trailhead	1	No	0.00	DELA_C2_110 7
T500	Sign	1	No	0.00	DELA_C2_111 1
T500	Lookout/Ob Deck	1	No	0.00	
T500	Bench	2	No	0.00	
T500	Sign	2	No	0.05	DELA_C2_111 2
T500	Begin Section	1	No	0.08	DELA_C2_111 4
T500	Begin Section	1	No	0.18	DELA_C2_111 5
T500	Begin Section	1	No	0.41	DELA_C2_111 6
T500	Begin Section	1	No	0.94	DELA_C2_111 8
T500	Bench	1	No	0.95	
T501	Trailhead	1	No	0.00	DELA_C2_111 3
T501	Bench	1	No	0.04	

sf - square feet

If - linear feet

cf - cubic feet

Detroit Lakes WMD Trail Location Map



HQ/VC

Trails ID

Station Name: Detroit Lakes WMD Org Code: 32586

Trail Number	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T500	Prairie Marsh Interpretive Trail	Admin Road	10058635	0.98	From Headquarters Parking (Rte 947) to End of Loop
T500	Prairie Marsh Interpretive Trail	Asphalt	10058635	0.08	From Headquarters Parking (Rte 947) to End of Loop
T500	Prairie Marsh Interpretive Trail	Gravel	10058635	0.10	From Headquarters Parking (Rte 947) to End of Loop
T501	Boardwalk Trail	Boardwalk	10012158	0.04	From Prairie Marsh Hiking Trail to End of boardwalk

TRAIL CONDITION



	0.1	0	0.	1 0.2		0.3 I Miles	5			
	Excellent	Go	od	Fair		Poor		Very Poo	or 💮	Admin Road
	Begin Section Trailhead	<u> </u>		k Dam ning Wall		Step Fe		\bowtie	Gate Bridge	W E
H Kr	Trail Sign	1		d Trail Structure	₩	Min. Wi		7	Bench	s s
	Drainage Structure		Wate	Bar	+	Intersec	ction	×	Other	Station Boundary

Trail Name: Prairie Marsh Interpretive Trail Refuge Name: Detroit Lakes WMD

Trail Number: T500 Region: 3 Total Length: **1.16 Miles**

Section Number	001	002	003	004	005
Section Length (miles)	0.08	0.10	0.23	0.53	0.22
SAMMS Number	10058635	10058635	10058635	10058635	10058635
Rating Date	07/12/2006	07/12/2006	07/12/2006	07/12/2006	07/12/2006
Trail Section Information					
Trail Class	TC5	TC4	TC4	TC4	TC4
Surface Type	Asphalt	Gravel	Admin Road	Admin Road	Admin Road
Surface Firmness	Paved	Hard	Firm	Firm	Hard
Width (inches)	95	102	120	120	120
Average Grade (%)	2.2	2.2	2.2	2.2	2.2
Average X-slope (%)	4.10	4.10	4.10	4.10	4.10
Trail Condition Information					
Deferred Maintenance					
CRV	\$23,713	\$24,817			
FCI	0.00	0.00			
Condition	Excellent	Excellent			

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$48,530	0.00	Excellent

TRAIL CONDITION





Trail Name:Boardwalk TrailRefuge Name:Detroit Lakes WMDTrail Number:T501Region: 3

 Section Number
 001

 Section Length (miles)
 0.04

 SAMMS Number
 10012158

 Rating Date
 07/12/2006

 Trail Section Information
 TC5

 Surface Type
 Boardwalk

 Surface Firmness
 Hard

 Width (inches)
 96

 Average Grade (%)
 2.3

 Average X-slope (%)
 3.70

Trail Condition Information

Deferred Maintenance
CRV \$46,314
FCI 0.00
Condition Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$46,314	0.00	Excellent

Total Length: 0.04 Miles

TRAIL DEFICIENCY

No Deficiencies

TRAIL NUMBER: T500 STATION: Detroit Lakes WMD

DATE: 07/12/2006



Photo # DELA_C2_1107 - MP 0.00 - Trailhead

TRAIL NUMBER: T500 STATION: Detroit Lakes WMD



Photo # DELA_C2_1111 - MP 0.00 - Sign

TRAIL NUMBER: T500 STATION: Detroit Lakes WMD

DATE: 07/12/2006



Photo # DELA_C2_1112 - MP 0.05 - Sign

TRAIL NUMBER: T500 STATION: Detroit Lakes WMD



Photo # DELA_C2_1114 - MP 0.08 - Begin Section

TRAIL NUMBER: T500 STATION: Detroit Lakes WMD

DATE: 07/12/2006



Photo # DELA_C2_1115 - MP 0.18 - Begin Section

TRAIL NUMBER: T500 STATION: Detroit Lakes WMD



Photo # DELA_C2_1116 - MP 0.41 - Begin Section

TRAIL NUMBER: T500 STATION: Detroit Lakes WMD

DATE: 07/12/2006



Photo # DELA_C2_1118 - MP 0.94 - Begin Section

TRAIL NUMBER: T501 STATION: Detroit Lakes WMD



Photo # DELA_C2_1113 - MP 0.00 - Trailhead

Glossary of Terms and Abbreviations

Acc Info Accessibility information available at trailhead.

Action Action required to correct deficiency.

Admin Road Administration Road. Admin Roads signed and

advertised as trails are included in the trail inventory but

a condition assessment is NOT done.

Alt SAMMS SAMMS number of Alternate Facility Type.

Alt Type Alternate Facility Type. Trail lies on a feature such as a

levee, dam, administrative road or bridge, which has a

separate SAMMS number.

AvgGrade The average grade of the trail (%). The average of five

measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

AvgSlope The average cross-slope of the trail (%). The average of

five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

Check Dam A small dam constructed across a drainage ditch, swale,

or channel to lower the speed of concentrated flows.

Condition Subjective rating of trail based on Facility Condition

Index (FCI):

FCI </= - .01 = Excellent FCI .02 - .05 = Good FCI .06 - .10 = Fair FCI .11 - .20 = Poor FCI > - .20 = Failed

Crib Wall Retaining wall.

Current

Replacement Value

(CRV)

The value of an asset determined by the estimated cost of

replacing it.

Def type Deficiency Type: Trail Structure, Drainage, Erosion,

Obstacle, Trail Location, Other.

Deferred

Maintenance (DM)

Maintenance that was not performed when scheduled.

i

Elem ID Unique identifier for each trail section: Org Code-Trail

Number-Section Number.

Facility

Condition Index (FCI)

DM/CRV

Grouped Features Grouped features include non-unique signs (mileposts,

interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the "quantity"

field of the data dictionary.

Info Type Type of accessibility information available at trailhead:

brochure, sign or other.

Item Item on which the "Action" (see above) will be

performed.

Manage_Use Managed use of the trail: HIKE, BIKE, NSPC (non-

specified), PACK, POR (portage), SNOWSHOE, XSKI

(cross-country ski), OTHER.

MP Distance of a trail feature or deficiency from the

Trailhead.

Puncheon Log footbridge used in area of poor drainage.

Raised Trail Structure Boardwalk, Turnpike, Puncheon.

T Class Trail Class: I-V (see Appendix? for trail class

descriptions).

Tr Desig Trail Designation: Standard (Std), National Historic Trail

(NHT), National Recreation Trail (NRT), National

Scenic Trail (NST).

Turnpike Trail tread elevated with dirt, rock or other aggregate

from parallel side ditches and held in place by logs.